

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4937	DATE	Apr.15, 2021
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	On the fastening surface of the rear stabilizer bracket and the car body, the bolt loosens during the use process, and a noise may occur caused by a gap in the mounting portion. If you continue to use it, the bolt may fall off, and in the worst case, the bracket may damage the peripheral parts.		

DBA-GT3	「XV」	2017 ~ 2019	16,634
DBA-GT7		2017 ~ 2019	39,953
5AA-GTE		2018 ~ 2019	5,671
5BA-SK9	「Forester」	2018 ~ 2019	19,025
5AA-SKE		2018 ~ 2019	15,277
		TOTAL	96,560