

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4942	DATE	Apr.19, 2021
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>In the front windshield glass and the back door window glass, the adhesion strength of the glass may be insufficient, due to the improper application of the adhesion bond primer.</p> <p>Under this condition, water leakage into the cabin may occur and the glass may be detached from the adhesion bond in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
3BA-JB64W	JIMNY	2020	71	
3BA-JB74W			30	
		TOTAL	101	