

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4941	DATE	Apr.23 2021
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In a crane vehicle</p> <p>① The power steering hose and tie rod may interfere with each other due to the improper mounting position of the power steering hose.</p> <p>② The power steering hose and tie rod may interfere with each other due to the improper mounting angle between the steering cylinder and the ball end.</p> <p>Therefore, if the power steering hose is used as it is, the power steering hose may be worn, and in the worst case, a hole may be formed in the power steering hose to increase the steering force.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
KA4120	—	2019~2020	8	①②
		2020~2021	11	②
TOTAL			19	