## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	4945	DATE	April 27, 2021	
MANUFACTURER	SUZUKI MOTOR CORPORATION			
DESCRIPTION OF DEFECT	Due to insufficient corrosion resistance of resistor for wheel speed sensor power supply circuit in the Speedometer Assy, resistor may cause poor conduction by corrosion, the wheel speed sensor may lose electric power supply.  Therefore, the wheel speed sensor may not function and the speedometer and odometer may not operate.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-CH41A	BURGMAN	2018-2020	1,770
		TOTAL	1,770