VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4932	DATE	2021/4/28
MANUFACTURE	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	-		
	Because of improper wiring of electrical in a rotary snowplow, Part of the electrical wiring is melted by the heat of the exhaust gas from tail pype. Therefore, if the electrical wiring is short-circuited, the fuse will blow and In the worst case, the engine may stop and restart may not be possible.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NR1B	NR32P	2018~2019	17
		TOTAL	17