

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5115	DATE	March 31,2022
MANUFACTURER	AICHI Corporation		
DESCRIPTION OF DEFECT	In some (but not all) Digger Derrick vehicles, due to the improper mounting position of the large rear reflector, winch hooks are placed in the area of geometric visibility according to Article 38-2 of the Safety Standards of the Act on Vehicles for Road Transportation. Therefore, the mounting position of the large rear reflector does not meet such safety standards. Mounting pedestals will be added to all vehicles to change the mounting position of the large rear reflector.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-GD7JGAA	HINO RANGER	2012 - 2016	46
QKG-FE7JGAA	HINO RANGER	2013 - 2014	2
SKG-FSR90S2	ISUZU FORWARD	2012 - 2016	32
TOTAL			80