

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	5118	DATE	March 24, 2022
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	<p>With regards to the tail lamps for all-wheel-drive vehicles (snowplows) with rear lamp harness extended modification, due to the inappropriate water proofing process for the connecting part of the extended tail lamp harness, rain water and/or melted snow may infiltrate into the harness which may corrode the tail lamp module connector inside. Thus, the tail lamps may cause connecting failure or short circuit which might cause tail lamps become unlighted or mis-lighted.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2DG-CF5AL	Quon	2018	19	
2DG-CZ5BL 2DG-CZ5BLKai		2018 - 2021	73	
			92	