## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIN No.	Gai – 3365	DATE	25 March, 2022		
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG				
	(Japanese Importer: Porsche Japan KK)				
DESCRIPTION OF DEFECT	There is a possibility that the wiring harness of the rear seat				
	belt buckle has been routed incorrectly during production of				
	the vehicle and thus interferes with the inner retaining				
	anchor bars of the LATCH/ISOFIX anchorage of the right				
	rear seat. If this is the case, the accessibility of the child seat				
	anchorage at the re	ear right is obstru	ght is obstructed and the child seat		
	cannot be properly secured.				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ZAA-J1MB	Taycan 4S	2021	77
ZAA-J1MC	Taycan Turbo		31
ZAA-J1MD	Taycan Turbo S		41
ZAA-J1NA1	Taycan		22
ZAA-J1NA1C	Taycan		29
ZAA-J1NA2	Taycan 4		2
ZAA-J1ND	Taycan Turbo S		1
		Total	203