

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5116	DATE	Mar 15th, 2022
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	If the wheel loader is kept to operate with filter frozen, engine oil will flow back into the combustion chamber, and engine rotation cause overrotate. The wheel loader will be not stop properly. In the worst case, there is a possibility that engin is damage when keep to operate by overrotate.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Kubota	「R430E」	R430E-10001~R430E-11022 Aug 5th 2016 ~Feb 28th 2022	889
	「6SDTL8」	R430E-10005~R430E-10331 Aug 8th 2016 ~Jan 15th 2018	133
	「R530E」	R530E-10001~R530E-10940 Oct 6th 2016 ~Feb 25th 2022	926
	「6SDTL10」	R530E-10020~R530E-10259 Sep 29th 2016 ~Feb 15th 2018	14
	「R630E」	R630E-10001~R630E-10231 2016 Aug 9th ~2022 Feb 28th	214
	「6SDTL12」	R630E-10004~R630E-10051 Sep 8th 2016 ~Sep 25th 2017	16
		TOTAL	2192