

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3361	DATE	11 March, 2022
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Internal function test have shown that the functionality of the oxygen sensor will not be consistently met over time, particularly at higher mileages or due to high thermal loads during race track use. Under certain conditions, this can cause an error messages “Engine control fault” to be displayed in the instrument cluster and the Check engine light will be activated. Compliance with the emission limits is ensured at all times. To correct this, the DME control unit on the affected vehicles must be reprogrammed with an updated data record.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-991MA175-	911 Speedster	2019	32
		Total	32