

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5105	DATE	Mar-1-2022
MANUFACTURER	YAMABIKO CORPORATION President & C.E.O. Hiroshi Kubo		
SUMMARY OF DEFECT	A cam plate, which is a component of the brake, is not properly manufactured, causing the cam plate to potentially crack. Therefore, if you continue to use it as it is, the cracked cam plate could cause the brake to malfunction allowing the machine to not adequately stop.		

TYPE	COMMERCIAL NAME	MODEL	NUMBER OF
		YEAR	VEHICLES
		RECALLED	
S55D	KIORITZ SPEED SPRAYER	2010~2021	925
	SSV553F		
S53B	KIORITZ SPEED SPRAYER	2011~2021	434
	SSVH535F		
S65A	KIORIZ SPEED SPRAYER	2012~2021	351
	SSV654F		
S54D	KIORIZ SPEED SPRAYER	2015~2021	531
	SSV5045F		
S52E	KIORIZ SPEED SPRAYER	2015~2019	6
	SSEV5021F		
		TOTAL	2,247