

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5106	DATE	Mar-1-2022
MANUFACTURER	YAMABIKO CORPORATION President & C.E.O. Hiroshi Kubo		
SUMMARY OF DEFECT	Since the design of the flasher unit of the turn signal is incorrect, the driver may not be warned if the turn signal is not working such as a disconnection. Therefore, there is a risk of the operator continuing to drive without noticing a failure of the turn signal.		

TYPE	COMMERCIAL NAME	MODEL	NUMBER OF
		YEAR	VEHICLES
		RECALLED	
S55D	KIORITZ SPEED SPRAYER	2010～2021	925
	SSV553F		
S53B	KIORITZ SPEED SPRAYER	2011～2021	434
	SSVH535F		
S65A	KIORIZ SPEED SPRAYER	2012～2021	352
	SSV654F		
S54D	KIORIZ SPEED SPRAYER	2015～2021	531
	SSV5045F		
S52E	KIORIZ SPEED SPRAYER	2015～2019	6
	SSEV5021F		
SA-S66B	KIORIZ SPEED SPRAYER	2006～2008	30
	SSV665FSC		
		TOTAL	2,278