VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No	5140	DATE			April-27-2022		
MANUFACTURER	PABCO CO "LTD						
DESCRIPTION OF DEFECT	Due to the improper bracket shape of the spare tire installing device that is installed on the side of the chassis frame of the rear overhang part of the heavy duty truck, some of the spare tire installing devices do not have sufficient strength. For that reason, due to vibrations during running, the spare tire installing device may have a crack and in the worst case, the installing part may break off causing drop of the device as well as the spare tire, resulting in obstructing other vehicles' running.						
TYPE	COMMERCIA	L NAME	MODEL YEAR RECALLED				NUMBER OF VEHICLE
2KG-FR1EHG	HINO PROFIA	2018		~	2019	4	
2KG-FS1EHA			20	019		1	
2KG-FW1EHG			20	018		4	
2PG-FR1AHG		2018		~	2019	8	
2PG-FR1AJA			20	018		2	
2PG-FW1AHG		2017		~	2019	7	
2PG-FW1AHJ		2018		~	2019	5	
2PG-FW1EHG			20	018		2	
2PG-FW1EHJ			20	018		1	
2RG-FR1AHG			20	018		2	
2RG-FW1AHG		2017		~	2019	11	
2RG-FW1AHJ	1			20	018		1
	TOTAL						48