

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5139	DATE	Apr.22 2022
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	For electrical wiring of snow sweepers, the wire coating may be melted by the heat of the engine exhaust manifold due to improper wire routing of the alternator wiring of the engine for work. Therefore, if the engine is continued to be used as it is, the core wire may be exposed and short-circuited. And the wire coating may ignite resulting in a vehicle fire in worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
2DG-CZ5BL 改	—	2018~2019	5	
QDG-CZ5YL 改		2017	1	
TOTAL			6	