

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	5134	DATE	April 21, 2022
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	<p>With regards to the parking brake air pressure sensor for heavy-duty-trucks, due to the inappropriate manufacturing process, some electric conductive foreign matter residue on the sensor circuit board may cause short-circuit and/or operation failure. Thus, the parking brake operation display may become mis-lighted or unlighted. In the worst case scenario, because of the brake operation lamp mis-lighting, the vehicle might move unexpectedly when the parking brake is released.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CD4BA 2PG-CD4BAKai	Quon	2018 - 2020	61	
2PG-CD4CA 2PG-CD4CAKai		2018 - 2020	67	
2PG-CD5AL		2017 - 2020	35	
2PG-CD5BA		2017 - 2020	333	
2PG-CD5BL 2PG-CD5BLKai		2017 - 2020	321	
2PG-CD5CA 2PG-CD5CAKai		2017 - 2020	4,179	
2PG-CD5CE		2018 - 2020	449	
2PG-CD5CL		2017 - 2020	366	
2DG-CF5AL		2018 - 2020	174	
2PG-CG4CA 2PG-CG4CAKai		2018 - 2020	99	
2PG-CG5AA		2020	1	
2PG-CG5BA		2017 - 2020	42	
2PG-CG5BE 2PG-CG5BEKai		2018 - 2020	11	
2PG-CG5BL		2018 - 2020	8	
2PG-CG5CA 2PG-CG5CAKai		2017 - 2020	8,619	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CG5CE	Quon	2018 - 2020	632	
2PG-CG5CL		2017 - 2020	367	
2PG-CV4BA		2020 - 2021	4	
2PG-CW4AL		2018 - 2020	182	
2PG-CW5AL		2017 - 2020	2,115	
2PG-CW5BL 2PG-CW5BLKai		2017 - 2020	620	
2PG-CW5CA 2PG-CW5CAKai		2017 - 2020	410	
2PG-CW5CL 2PG-CW5CLKai		2017 - 2020	522	
2PG-CX5BA 2PG-CX5BAKai		2017 - 2020	180	
2PG-CX5BL 2PG-CX5BLKai		2017 - 2020	118	
2DG-CZ5BL 2DG-CZ5BLKai		2018 - 2020	557	
2PG-GK5AAB 2PG-GK5AABKai		2017 - 2020	4,583	
2PG-GK5AAD 2PG-GK5AADKai		2017 - 2020	1,486	
2PG-GK5AAE 2PG-GK5AAEKai		2017 - 2020	306	
2PG-GK5AAK		2018 - 2020	5	
2DG-HF5AL	-	2018 - 2020	6	
2DG-HZ5BL		2018 - 2020	11	
2DG-SF5AL		2018 - 2020	6	
2DG-SZ5BL		2018 - 2020	10	
			26,885	