

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3392	DATE	April 21, 2022
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	The engine compartment cover on the power unit can become detached from its retainers depending on service life and vehicle use (very sporty driving style or poor road surfaces). If the engine compartment cover is not securely attached, it can potentially come into contact with the hot area of the turbocharger, leading to smoldering damage or even a fire in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-FVDNPF	Audi TT 45Tq	2022	101
		Total	101