

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5133	DATE	April 14 ,2022
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain light duty trucks, the electric circuits in EDU (Electronic Driving Unit) are inadequate. This may cause the EDU to malfunction affected by the noise produced from the vehicle's electric parts. Consequently, the engine warning lamp may turn on, leading to the engine stall in the worst case.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-NHR88A 2RG-NHR88AN	[ELF]	2019-2021	2,137
2RG-NHS88A 2RG-NHS88AN		2019-2021	1,022
2RG-NJR88A 2RG-NJR88AD 2RG-NJR88AN 2RG-NJR88N 2SG-NJR88AN		2019-2021	7,079
2RG-NJS88A 2RG-NJS88AN		2019-2021	939
2PG-NKR88N 2PG-NKR88R 2RG-NKR88A 2RG-NKR88AD 2RG-NKR88AN 2RG-NKR88AR 2RG-NKR88N 2RG-NKR88R 2SG-NKR88AN		2019-2021	13,016
2PG-NKR88YN 2RG-NKR88YN		2019-2021	760
2PG-NKS88A 2PG-NKS88AD 2PG-NKS88AN 2RG-NKS88A 2RG-NKS88AN		2019-2021	1,969

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2RG-NLR88AN 2RG-NLR88AR 2RG-NLR88N 2SG-NLR88AN	[ELF]	2019-2021	6,801	
2RG-NLS88AN 2RG-NLS88AR		2019-2021	393	
2PG-NMR88N 2PG-NMR88R 2RG-NMR88AN 2RG-NMR88AR 2RG-NMR88N 2RG-NMR88R 2SG-NMR88AN 2SG-NMR88N		2019-2021	5,972	
2PG-NMS88AN 2PG-NMS88AR 2RG-NMS88AN 2RG-NMS88AR		2019-2021	811	
2RG-NNR88AN 2RG-NNR88AR 2RG-NNR88N		2019-2021	480	
2RG-NNS88AN		2019-2021	43	
2PG-NPR88AN 2PG-NPR88AR 2PG-NPR88N 2RG-NPR88AN 2RG-NPR88AR 2RG-NPR88N 2SG-NPR88AN		2019-2021	12,292	
2PG-NPR88YN 2RG-NPR88YN		2019-2021	4,635	
2PG-NPS88AN 2PG-NPS88AR 2RG-NPS88AN 2RG-NPS88AR		2019-2021	1,045	
2RG-AHR88A 2RG-AHR88AN		[ATLAS]	2019-2021	798
2RG-AHS88A 2RG-AHS88AN			2019-2021	313
2RG-AJR88A			2021	1
2RG-LHR88A 2RG-LHR88AN		[TITAN]	2019-2021	666
2RG-LHS88A 2RG-LHS88AN	2019-2021		158	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2RG-LJR88A 2RG-LJR88AD 2RG-LJR88AN 2RG-LJR88N	[TITAN]	2019-2021	268	
2RG-LJS88A 2RG-LJS88AN		2019-2021	27	
2RG-LKR88A 2RG-LKR88AD 2RG-LKR88AN 2RG-LKR88AR 2RG-LKR88N 2RG-LKR88R		2019-2021	299	
2PG-LKR88YN		2020	1	
2PG-LKS88AD 2PG-LKS88AN 2RG-LKS88A		2019-2021	28	
2RG-LLR88AN 2RG-LLR88AR 2RG-LLR88N		2019-2021	103	
2RG-LLS88AR		2020-2021	7	
2RG-LMR88AN 2RG-LMR88AR 2RG-LMR88N 2RG-LMR88R		2019-2021	70	
2RG-LMS88AN 2RG-LMS88AR		2019-2021	7	
2RG-LNR88AN 2RG-LNR88AR		2019-2021	32	
2RG-LNS88AN		2019-2020	2	
2RG-LPR88AN 2RG-LPR88AR		2019-2021	150	
2RG-LPR88YN		2019-2021	48	
2PG-LPS88AN 2PG-LPS88AR 2RG-LPS88AN 2RG-LPS88AR		2019-2021	15	
			TOTAL	62,387

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2RG-NJR88A	[ELF]	2019	1	
2PG-NKR88N 2RG-NKR88A 2RG-NKR88AD 2RG-NKR88AN 2RG-NKR88R		2019	11	
2PG-NKR88YN 2RG-NKR88YN		2018-2019	13	
2RG-NKS88A		2019	1	
2RG-NLR88AN 2RG-NLR88N		2019	6	
2RG-NLS88AN		2019	1	
2RG-NMR88AN 2RG-NMR88AR 2RG-NMR88N		2019	9	
2PG-NMS88AN		2019	1	
2RG-NPR88AN 2RG-NPR88AR 2RG-NPR88N		2018-2019	25	
2PG-NPR88YN 2RG-NPR88YN		2018-2019	67	
2PG-NPS88AN		2019	1	
		TOTAL	136	

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
EDU	8-97546790-0 8-97546790-1 8-97546792-0	2019-2022	10
		TOTAL	10