VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5131	DATE	April.13.2022
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	On the cowl louver in the subject hybrid vehicles, due to improper waterproof property of the service hole cover in the cowl louver, there is a possibility that the waterproof may be decreased over time, causing water to enter in the cylinder bores through the injector installation area of the engine under heavy rain condition. If this were to occur, the connecting rods can be damaged, leading to abnormal noise, and in the worst case, the engine could be damaged, resulting in the vehicle becoming inoperative.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-NHP170G	[SIENTA]	2015-2022	259,991
6AA-NHP170G			
		TOTAL	259,991