

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5132	DATE	Apr.13.2022
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>#1. In Vehicle Stability Control system (VSC), due to an improper control program for the VSC, the VSC will not return to the default ON setting at the next ignition cycle if the brake is continuously pressed between when the vehicle is shut off and then restarted under VSC OFF condition. If this were to occur, the VSC OFF light will illuminate and VSC will not be activate.</p> <p>#2. In the body panels around the shock absorber mounting areas in the engine compartment, due to improper settings of the welding machines, there is a possibility that these panels may have missing welds. If this occurs, cracks and breakage could occur on the body panels around the front shock absorbers mounting areas, resulting in a loss of vehicle driving stability.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6AA-AXUH80	[HARRIER]	2020-2022	43,404	#1
6AA-AXUH85			18,874	
6AA-AXAH52	[RAV4]	2021-2022	351	#1
6AA-AXAH54			4,108	
6LA-AXAP54	[RAV4 PHV]	2020-2022	5,910	#1
ZBA-JPD20	[MIRAI]	2020-2022	3,336	#1
3DA-FJA300W	[LAND CRUISER]	2021-2022	1,432	#1
3BA-VJA300W			1,373	
5BA-AAZA20	[NX250]	2021-2022	170	#2
5BA-AAZA25			47	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
5BA-TAZA25	[NX350]	2021-2022	335	#2
6AA-AAZH20	[NX350h]	2021-2022	1,037	#1
			1,051	#1 and #2
6AA-AAZH25			608	#1
			643	#1 and #2
6LA-AAZH26	[NX450h+]	2021-2022	162	#1
			1,173	#1 and #2
6AA-GVF50	[LS500h]	2020-2022	1,762	#1
6AA-GVF55			1,911	
3BA-VJA310W	[LX600]	2021-2022	474	#1
		TOTAL	88,161	

#1: 87,609

#2: 3,419

#1 and #2: 2,867