

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5130	DATE	Apr.12 2022
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty touring buses, the swing door lower harness is not properly routed, so the harness may interfere with peripheral parts when the door is opened and closed, resulting in excessive bending. If the vehicle continues to be used in this condition, wires in the harness may break and malfunction of electrical components (pilot lamps, side turn signal lamps, door glass heater elements) may occur. In the worst case, unusual odors or smoke may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2TG-MS06GP	「FUSO AERO ACE」	2019~2021	873
	「FUSO AERO QUEEN」	2019~2021	137
TOTAL			1,010