VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI3378	DATE	11.Apr, 2022	
MANUFACTURE	SCANIA CV AB			
	(Japanese Importer: Bando motors Co.Ltd.)			
DESCRIPTION OF DEFECT	In some air pressure control systems (APS), the airtightness of the air pressure cannot be maintained due to improper design of the air dryer regeneration control valve. Therefore, there is a risk that air leakage will occur, the warning light will light up, or the air pressure will not rise after the engine is started, and the parking brake will not be released, making it impossible to drive.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	BRONTOX56	YS2P6X20002170789 2020/9/3	1
	MOOG140	YS2P6X20002168939~YS2P6X20005559093 2020/1/29~2020/6/25	2
	MOOG1750	YS2P8X40005596425 2021/5/6	1
	MOOG180	YS2P8X40005582239~YS2P8X40005596393 2020/7/29~2020/4/8	2
	IDROGRU IB70S	YS2P6X40005556269~YS2P6X40005589940 2019/11/19~2020/11/4	8
	IDROGRU IB140S	YS2P8X40009269977~YS2P8X40009273680 2020/11/4~2021/3/4	3
	LPGRS series Truck	YS2S6X60002169468~YS2S6X60002170728 2020/2/27~2020/4/22	15
TOTAL 1 TYPE	TOTAL 7 MODEL	TOTAL 2019/11/19~2021/5/6	32