

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	5128	DATE	2022/4/7
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		With regards to the heat shields for heavy duty tractors, the incompatible shape may in some cases be interfering with the oil cooler hose of the transmission caused by vibration stresses while driving. If the vehicle continues to be operated, this can cause the oil cooler hose of the transmission to be damaged, and furthermore the generated cracks, becoming unable to withstand the oil pressure, lead to a faulty transmission with a corresponding oil leakage. In an extreme case, this may result in poor traveling.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-EXD52CD	"GIGA"	March 21, 2019 ~ October 26, 2019	2
2KG-EXD52CD		February 4, 2020	1
2PG-EXD52CE		January 15, 2019 ~ October 27, 2020	25
2DG-EXY52CK		November 27, 2019	1
		TOTAL	29