

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5153	D A T E	May.26. 2022
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Since the EGR pressure sensor mounted on the exhaust gas recirculation device (EGR) lacks resistance to exhaust gas, corrosion due to exhaust gas may cause the sensor output abnormally, turn the warning light on, cause acceleration failure, and in the worst case, the engine may not be able to start.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4BA-VN5	「LEVORG」	2020~2022	32,986
4BA-SK5	「FORESTER」	2020~2022	14,313
4BA-BT5	「LEGACY」	2021~2022	5,539
TOTAL			52,838