VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

		•	
GAI-3406	DATE	May 26, 2022	
Audi			
(Japanese Importer: VOLKSWAGEN Group Japan K.K.)			
The level of oil in the gearbox may be insufficient. Due to insufficient oil in the			
gearbox, an interruption in power flow in the drive train due to clutch slip			
cannot be ruled out. A message may be shown in the instrument cluster in			
this context. During extreme driving manoeuvres (e.g. if the vehicle is driven			
on a racetrack), oil foam may form and could escape from the gearbox			
breather. It cannot be ruled	out that this could result in	a fire.	
	(Japanese Import The level of oil in the gearbo gearbox, an interruption in cannot be ruled out. A mes this context. During extreme on a racetrack), oil foam r	Audi (Japanese Importer: VOLKSWAGEN Group The level of oil in the gearbox may be insufficient. Due gearbox, an interruption in power flow in the drive tr cannot be ruled out. A message may be shown in the this context. During extreme driving manoeuvres (e.g.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-4SDMWF	Audi R8 V10	2021	1
		Total	1