

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	5 1 5 1	DATE	May23.2022
MANUFACTURER	NICHIGO CORPORATION		
DESCRIPTION OF DEFECT	<p>In the electrical equipment of rotary snowplows, Due to improper wiring fixing method, The alternator wiring and ground wiring rub against the wiring clamp due to running vibration. and the coating may be damaged. Therefore, if it is continued to be used as it is, a short circuit between the damaged part and the clamp, and in the worst case, a fire may occur.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-R03F	HTR308A	2018~2022 R03F-0002~ R03F-0266	260
		TOTAL	260

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where