VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5152	DATE	May 19,2022		
MANUFACTURER	SUZUKI MOTOR CORPORATION				
DESCRIPTION OF DEFECT	The front door latch may deform in the event of the vehicle collision and the side air bag deployment, due to the improper configuration of the door latch and the striker. As the result, the door latch and the striker may disengage and the front door may open unintendedly in the worst case.				

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
DAA-MH55S	WACON D	2017~2020	17,972	The vehicle equipped with the side air bag
4AA-MH55S	WAGON R	2020~2022	3,658	
		TOTAL	21,630	