

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3405	DATE	May 19th, 2022
MANUFACTURE	McLaren Automotive (Japanese Importer : McLaren Automotive Asia Pte Ltd.)		
DESCRIPTION OF DEFECT	The rear wheel arch liner is in close proximity to the rear brake pad sensor wiring, under some rear suspension condition, the wiring may clash with the rear wheel arch liner. If the wiring damaged, it may cause the brake warning lamp ON.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	McLaren ELVA	2021	8
		TOTAL	8