

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5141	DATE	May 12,2022
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to a manufacturing failure, some lubber caps on the external switch to open and close the power slide door may be cracked, and this may cause conduction by moisture to enter inside to the switch through the cracked portion. As a result, the slide door may open unintendedly when driven at very low speed or when a vehicle is stationary.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-CV1W	「DELICA」	2015~2019	33,886
3DA-CV1W		2019~2020	21,884
DBA-CV2W		2015~2019	3,221
DBA-CV5W		2015~2019	4,132
		TOTAL	63,123

The parts for which the vehicle can not be identified because it was shipped as service parts

Part Name	Part No.	Delivery Period of the part	Quantity
COVER,RR DOOR OUTSIDE HANDLE RH	5746A189	2020~2022	21
COVER,RR DOOR OUTSIDE HANDLE LH	5746A190	2020~2022	21
COVER,RR DOOR OUTSIDE HANDLE RH	5746A187HB	2020	7
COVER,RR DOOR OUTSIDE HANDLE RH	5746A187HC	2020~2022	4
COVER,RR DOOR OUTSIDE HANDLE RH	5746A187WA	2020~2022	17
COVER,RR DOOR OUTSIDE HANDLE RH	5746A187XA	2020~2022	10
COVER,RR DOOR OUTSIDE HANDLE RH	5746A187XB	2020~2021	9
COVER,RR DOOR OUTSIDE HANDLE LH	5746A188HB	2020~2022	2
COVER,RR DOOR OUTSIDE HANDLE LH	5746A188HC	2020	4

COVER,RR DOOR OUTSIDE HANDLE LH	5746A188WA	2020~2021	3
COVER,RR DOOR OUTSIDE HANDLE LH	5746A188XA	2020~2022	18
COVER,RR DOOR OUTSIDE HANDLE LH	5746A188XB	2020~2021	5