

**Form No. 4: Summary of Recall Campaign in English (Related to Article 2)**

**Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-3409	Date	Jun. 7, 2022
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	<p>1. Engine accessory drive belt can snap due to auto tensioner failure, resulting in loss of electrical charging to the vehicle batteries.</p> <p>2. Due to PCM program failure, Engine start is run by BISG. Vehicles in this condition will continue to exhibit suitable and adequate warnings and the vehicle will remain driveable for a period of time. Should the warnings be ignored the 12V system will become depleted to the point it can no longer supply the engine control systems with sufficient electrical power, leading to possible engine cut out or inability to start the vehicle.</p> <p>1. Replace the belt and tensioner 2. update the PCM software.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
3CA-DC2NC	F-PACE	2021-2022	107
3CA-DF2NB	E-Pace	2021-2022	216
3CA-JA2ND	XE AWD	2021-2022	59
3CA-JB2ND	XF AWD	2021-2022	64
3CA-JBS2ND	XF Sport break	2021-2022	26
3CA-LC2ND	Discovery Sport	2021-2022	160
3CA-LY2NAC	Velar	2021-2022	30
3CA-LY2NCC		2021-2022	135
3CA-LZ2NB	Evoque	2021-2022	216
Total			1,013

(JIS A4 size)