

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3452	DATE	July 21, 2022
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	The distance between the tank level sender and a breather line in the tank may be too small. As a result, the sender may get caught on this line in the tank. This leads to the drop in the fuel level not being detected while the vehicle is being operated and therefore to an incorrect fuel level and remaining range being displayed in the instrument cluster. In the worst case, the fuel in the tank is used up completely, the vehicle will stop without prior warning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-F2DJPA	Audi RS7 SB Air-Suspension	2021	45
3AA-F2DJPF	Audi RS6 Avant	2021	91
3AA-F2DJPL	Audi RS6 Avant Air-Suspension	2021	56
3AA-F2DJPS	Audi RS7 SB	2021	70
3AA-F2DKMA	Audi S7 SB	2020-2021	73
3AA-F2DKML	Audi S6	2020-2021	148
3AA-F2DKNF	Audi A6 45Tq	2020-2021	846
3AA-F2DKNS	Audi A7 SB 45Tq	2020-2021	531
3AA-F2DLZF	Audi A6 55Tq	2021	30
3AA-F2DLZS	Audi A7 SB 55Tq	2021	55
AAA-F2DLZF	Audi A6 55Tq	2019-2020	1,126
AAA-F2DLZS	Audi A7 SB 55Tq	2019-2020	1,279
		Total	4,350