VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	外-3444	DATE	July 13. 2022		
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.				
	In the main shift clutch of an agricultural tractor, the strength of main shift clutch plate is insufficiently examined because strength of the plate is insufficient. Therefore, there is a risk that clutch plate will be damaged by repeated operations of the 1st 2nd speeds of the main shift. If you continue to use it as it is, it worst case, you may not be able to drive at the 1st and 2nd shifts.				

TYPE	COMMERCIAL MODEL YEAR NAME RECALLED		NUMBER OF VEHICLE		
_	「JD-6155M」	2016~2021		59	
_	「JD-6195M」	2016~2021		108	
_	「JD-6195R」	2021		1	
			TOTAL	168	