

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3455	DATE	August 24 th 2022
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>1) It was found out that there is a software failure in the airbag control unit (ACSM). In the event of a fault, if a component of the restraint system, active pedestrian protection or crash shutdown of the high-voltage system fails, a Check Control message or AWL (airbag warning light) may not be displayed.</p> <p>2) Due to inappropriate software in integrated brake system (DCS/VIP), the system may fail in very limited local crossings in Japan, which may lead to vehicle slowing down, loss of power steering assist or popping up of various warning lights such as AWL (airbag warning light).</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-22BY20	「BMW 218d Active Tourer」	2022	1
ZAA-12CF89S	「BMW iX xDrive40」	2021~2022	289
ZAA-12CF89A		2022	7
ZAA-22CF89A	「BMW iX xDrive50」	2021~2022	93
ZAA-31CF93A	「BMW iX M60」	2022	3
		TOTAL	393