

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-3459	Date	2022/8/8
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	Engine mounting bolt may have been tightened to insufficient torque. Then the engine holding may be loosened and noise or excessive vibration can appear.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-JW2	「910」	2022	1
		TOTAL	1