VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	外 3507	DATE	31,Oct,2022
MANUFACTURE	Bombardier Recreational Products Inc.		
	(Japanese Importer : BRP Japan)		
DESCRIPTION OF DEFECT	The front sprocket manufacturing process is inadequate, and the contact surface between the sprocket and the output shaft is small. The contact surface between the sprocket and the output shaft is small. Therefore, the sprockets wear out prematurely. If the sprockets continue to be used as they are, they will no longer be able to transmit the vehicle's power and the vehicle will not be able to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NB	SPYDER RT	2BXNBCD10FV000087~ 2BXNBDD1XJV003965	429
		17,Nov,2014~16,Apr,2018	
RD	SPYDER F3	2BXRDCD10FV001557~ 2BXRDDE1XJV000039 17,Nov,2014~16,Apr,2018	496
RE	SPYDER F3-T,F3-LTD	2BXREDD10GV001014~ 2BXREDD1XJV002534 17,Nov,2014~16,Apr,2018	275
		TOTAL	1200