

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3496	DATE	October 27, 2022
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper surface finish quality of variable valve timing unit, some installation bolts become loose. As a result, valve timing control unit becomes broken; in the worst case, vehicle turns out as breakdown condition and not possible to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-AUCJZ	VW Golf 1.2/77kW	MY2014-MY2015	3
DBA-6RCJZ	VW Polo 1.2/66kW	MY2015	3
		Total	6