

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3514	DATE	November 21 st , 2022
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate software of steering wheel electronics, the Hands Off Detection (HOD) of the Lane Control Assistant (LSA) and Lane Change Assistant (SWA) does not comply with the regulation. When the steering wheel heating or interior heating is active, the system cannot clearly detect whether the driver's hands are on the steering wheel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-62BX15	「BMW 218i Active Tourer」	2022	206
3DA-22BY20	「BMW 218d Active Tourer」	2022	174
ZAA-12CF89A	「BMW iX xDrive40」	2021 - 2022	21
ZAA-12CF89S		2021 - 2022	349
ZAA-22CF89A	「BMW iX xDrive50」	2021 - 2022	121
ZAA-31CF93A	「BMW iX M60」	2022	7
		TOTAL	878