

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3525	Date	December 8, 2022
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the steering column switch, after a fall of the system voltage to below 6V (for example, after a cold engine start with low charge level of starter battery) the steering column control unit can diagnose an “electric fault” due to inappropriate program. As a result, the horn does not work until the next ignition cycle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-1TCZD	Golf Touran 1.4/110kW	MY2019	9
		Total	9