

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	GAI-3570	DATE	17.02.2023
MANUFACTURE	Ferrari SpA (Japanese Importer : Ferrari Japan K.K)		
DESCRIPTION OF DEFECT	Given the inappropriate laser marking of the data matrix on the engine connecting rod, it may happen that the connecting rod cracks due to the metal fatigue when the vehicle is used at extremely high engine revolutions for a long period. In the worst case scenario, the connecting rod may break.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-F152BE	812 Competizione	2022	1
		TOTAL	1