

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	外 3555	DATE	13. Feb. 2023
MANUFACTURE	DFSK (Japanese Importer : folofly inc.)		
DESCRIPTION OF DEFECT	At the steering shaft and steering gear assembly connection, the rubber material used for the dust cover is inappropriate. If it keep using, problems such as cracks may occur, and there is a risk that it will not satisfy the standards for the steering system. If you continue to use it for a long time in a cracked, the internal oil seal may deteriorate by dust then grease may leak out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
N/A	folofly F1 VAN	2021 ~ 2022	17
		TOTAL	17

【記入例】

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

輸入車のリコールの場合、Import に丸印を記入するか、Domestic に二重線を記入又は記載しない用にして下さい。

CAMPAIGN No.	GAI-	DATE	Domestic / Import Vehicles July 21, 2005
MANUFACTURE	(Japanese Importer :)		
DESCRIPTION OF DEFECT	<p>上段には自動車製作者の名称を記載して下さい。 下段には届出者の名称を記載して下さい。</p> <p>日付の記載は、月（英字）日（アラビア数字）、西暦の順でリコール届出年月日を記載して下さい。（リコール開始年月日を記入しないで下さい。）</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
		製作年のみの記載。 2005-2006	
		TOTAL	

Domestic Vehicles : 日本国内車両

Import Vehicles : 輸入車両

CAMPAIGN No. : 届出番号

DATE : 届出年月日

MANUFACTURE : 製作者名

DESCRIPTION OF DEFECT : 不適合状態

TYPE : 型式

COMMERCIAL NAME : 通称名

MODEL YEAR RECALLED : 対象車両の製作年

NUMBER OF VEHICLE : 対象車両数