

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3557	DATE	February 2, 2023
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	The distance between the tank level sender and a breather line in the tank may be too small. As a result, the sender may get caught on this line in the tank. This leads to the drop in the fuel level not being detected while the vehicle is being operated and therefore to an incorrect fuel level and remaining range being displayed in the instrument cluster. In the worst case, the fuel in the tank is used up completely, the vehicle will stop without prior warning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-F2DJPA	Audi RS7 SB Air-Suspension	2021-2022	7
3AA-F2DJPF	Audi RS6 Avant	2021-2022	5
3AA-F2DJPL	Audi RS6 Avant Air-Suspension	2021-2022	24
3AA-F2DJPS	Audi RS7 SB	2021	2
3AA-F2DKMA	Audi S7 SB	2021-2022	4
3AA-F2DKML	Audi S6	2021-2022	28
3AA-F2DKNF	Audi A6 45Tq	2021-2022	123
3AA-F2DKNS	Audi A7 SB 45Tq	2021-2022	69
3AA-F2DLZF	Audi A6 55Tq	2022	4
3AA-F2DLZS	Audi A7 SB 55Tq	2022	15
		Total	281