

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	外 3547	DATE	January 20 <sup>th</sup> ,2023
MANUFACTURE	Bombardier Recreational Products Inc. Japanese Importer : BRP Japan		
DESCRIPTION OF DEFECT	The harness located in the front fenders may be loose due to the locking clip was not installed properly at production line. As a result, the harness may rub on the tires, damage the covering of the harness, and cause a short circuit. If this happens, the engine will stop and vehicle stability systems including the anti-lock braking system (ABS) also becomes inoperative. This condition may increase the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2FF 2FG 2GG,2HH 2JG	Can-Am RYKER600 Can-Am RYKER900 Can-Am RYKER RALLY Can-Am RYKER SPORT	5 Feb 2019 to 5 Jul 2022	656
		TOTAL	656