

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3578	DATE	February 28, 2023
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	The collar of the wheel arch cover can become detached due to a torsional movement. As a result, the wheel arch cover may come loose and, in individual cases, become detached from the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-FYCWGA	Audi SQ5 Air-Suspension	2020	3
ABA-FYCWGS	Audi SQ5	2020	2
DBA-FYDAXA	Audi Q5 45Tq Air-Suspension	2018-2020	5
DBA-FYDAXS	Audi Q5 45Tq	2020	9
LDA-FYDETA	Audi Q5 40TDIq Air-Suspension	2020	10
LDA-FYDETS	Audi Q5 40TDIq	2020	56
		Total	85