

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3546	DATE	January 11, 2023
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	A component with insufficient strength, inside the fuel delivery unit may break while the vehicle is being driven due to pressure pulsations. The broken pieces may damage the sealing membrane in the unit. This fault causes the emission control system warning lamp to light up due to reduced fuel supply pressure. Depending on the extent of the damage, the engine may lose power suddenly, in the worst case, potentially resulting in a breakdown.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-4MDCBA	Audi Q7 55Tq Air-suspension	2020-2021	269
3AA-4MDCBS	Audi Q7 55Tq	2020-2021	24
3AA-F1DCBA	Audi Q8 55Tq Air-suspension	2021	137
3AA-F1DCBS	Audi Q8 55Tq	2021	1
AAA-F1DCBA	Audi Q8 55Tq Air-suspension	2019-2020	1,136
AAA-F1DCBS	Audi Q8 55Tq	2020	1
		Total	1,568