

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3593	DATE	March 30, 2023
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	Due to an error in the manufacturing process for the air spring strut, a groove in the area of the support mounting may not have been manufactured according to the specifications. This means that the circlip may not be securely seated in the groove. If the circlip slips out of the groove, air spring may be detached from the strut. As a result, the air will escape from the affected air spring strut, the spring function will be lost, the vehicle will drop on one side, and the operability of the steering may deteriorate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-FWEBGE	Audi RS e-tron GT	2022	7
		Total	7