## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai 3586	DATE	Mar 6th, 2023
MANUFACTURE	PEUGEOT MOTOCYCLES SAS		
	(Japanese Importer : aid	lea Co., Ltd.	)
DESCRIPTION OF DEFECT	The rubber seal for the wires of the taillight unit is not waterproof enough, when water gets into the unit and corrodes the LED connection, the light may not work properly, and when the unit continues to be used as is, either the taillight or the brake light or both have chance to stop operating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
F1ADBA	SPEEDFIGHT 50	2019 April- 2019 November	24
F2AGJC	SPEEDFIGHT 125	2018 March- 2019 November	112
		TOTAL	136