

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3576	DATE	March 01, 2023
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to a software error of the seat module, the initialization function may be lost, and the seat position might not be detected correctly. In this case, a red airbag warning light and a Check Control message informs the driver that the restraint systems are only available to a limited extent. In the event of an accident, the front passenger airbag, knee airbag and active head restraint are not triggered. The seat belt tensioner is fully available.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-22EH30	「BMW 740i」	2022	65
ZAA-32AW89	「ZAA-52EJ89」	2022	63
		TOTAL	128