

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3605	DATE	Apr. 26 th , 2023
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The fuel tank may have a welding fault on the lid of the mounting hole for the suction jet pump. Due to driving vibration etc., this may lead to the formation of cracks at the weld seam, where the fuel may leak from.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-8E15	BMW 318i	2016 - 2018	5,978
DBA-3B20	BMW 320i	2012 - 2013	5
DBA-8A20	BMW 320i	2016 - 2018	5349
DBA-3X20	BMW 320i GranTourismo	2016	11
DBA-8X20	BMW 320i GranTurismo	2016 - 2017	279
DBA-3X28	BMW 328i GranTurismo	2018	1
DBA-8A20	BMW 330i	2017	23
DBA-8B30	BMW 340i	2016 - 2018	170
DBA-3N20	BMW 420i	2014	1
DBA-4N20	BMW 420i	2016 - 2018	574
DBA-4D20	BMW 420i Gran Coupe	2016 - 2018	3,273
DBA-4N20	BMW 430i	2016 - 2017	42
DBA-4D20	BMW 430i Gran Coupe	2016 - 2017	92
DBA-4P30	BMW 440i	2016 - 2018	346
DBA-4E30	BMW 440i Gran Coupe	2016 - 2018	217
CBA-3C30	BMW M3	2016 - 2018	556
CBA-3C30	BMW M4	2016 - 2018	777
		TOTAL	17,694