

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)**Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-3615	Date	Jun. 13, 2023
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	The water pump pulley drive belt may become damaged or detach, which can allow the engine to overheat. An overheated engine can rupture the engine coolant elbow pipe, leaking coolant onto the turbocharger heat shield. Replace the engine coolant elbow.		

Type	Commercial name	Model year recalled	Number of vehicles
5LA-LG2YE	Range Rover	2019-2022	60
5LA-LGL2YE		2019-2021	10
5LA-LW2YC	Range Rover Sport	2018-2022	107
		2018-2022	177

(JIS A4 size)