## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domostic /Import Vehicles

CAMPAIGN No.	Gai-3664	DATE	27/July/2023	
MANUFACTURER	Automobiles Volv	Automobiles Volvo Car Corporation		
	(Japanese Import	(Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF	The ball joint conn	The ball joint connecting the Front Lower Control Arm (FLCA)		
DEFECT	with the steering knuckle may have been incorrectly			
	positioned. The FLC	positioned. The FLCA may separate from the knuckle on the		
	left-hand side.	left-hand side.		
	COMMERCIAL	MODEL	NUMBER OF	
TYPE	NAME	YEAR	VEHICLE	
		RECALLED		
VOLVO	[ C40]	2023	4	
		TOTAL	4	