

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	Gai-3637	DATE	Aug 31, 2023
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	In the alternator pulley, insufficient strength of the clutch carrier due to a defective molding process and inappropriate alternator voltage control settings in the engine control program, the alternator pulley may break and spin immediately after the engine starts. As a result, power generation failure may occur, a warning light or warning message may be displayed, and in the worst case, the engine may stall or the engine may not restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-DFM5P	Alpine A110	2019 - 2021	162
7BA-DFM5P1	Alpine A110	2020 -2021	80
7BA-DFM5P2	Alpine A110	2021	41
7BA-DFM5P3	Alpine A110	2021	12
ABA-DFM5P	Alpine A110	2018 -2020	556
		TOTAL	851